


FIG. 1



1/19




FIG. 2




FIG. 3





FIG. 4








FIG. 8









FIG. 9










FIG. 14



FIG. 15






FIG. 16





- HALF KNOT
- ENTRY (IN)
- EXIT (OUT)
- ⌘ HALF KNOT WITH WRAP AROUND
- ⋯ SINGLE KNOT
- ⌘ SUTURE BEADING (4 SQUARE KNOTS)

FIG. 17





FIG. 18



- HALF KNOT
- ENTRY (IN)
- EXIT (OUT)
- ⊗ HALF KNOT WITH WRAP AROUND
- SINGLE KNOT
- ⊗ SUTURE BEADING (4 SQUARE KNOTS)

FIG. 19




FIG. 20




FIG. 21




FIG. 22






FIG. 25





FIG. 28




FIG. 29







FIG. 30



17/19




FIG. 31

FIG. 32





FIG. 33

FIG. 34





FIG. 35